

Camberwell Drive Ashton-under-Lyne

The Coal Authority

Residents Meeting

Camberwell Drive – what happened?

- An incident occurred in December 2021, causing a hole to open in the public open space area
- The ground collapse was fenced and infilled with over 300 tons of stone
- The exact cause of the collapse is unknown but was thought to be linked to the recorded mine shaft
- We have continued to monitor the site and the surrounding road – this has shown no further movement
- Site has been maintained whilst we have looked into options







Listening to your feedback

- Following the last public meeting, we listened to the feedback from you and we have engaged a specialist consultant to undertake a review of the options available
- They have reviewed the shaft and the ground conditions and have assessed the options for the shaft
- Preliminary designs have been prepared to allow costings and impact to be assessed



Proposed solution





Plan of the proposed works

<u>KEY</u>

Approximate Treatment Working Area

Designated Area for Compound and Equipment Storage

Approximate Position of Ground Collapse



Community support

- Community liaison officer
- Regular communications
- Monitoring during works
- Property inspections
- Tameside Council



6

Timescales





Next steps

- Newsletter to wider community and those unable to attend tonight
 - Seek any further feedback and questions
- Hold discussions with immediately impacted residents
 - Personalised meetings/communications
- Finalise the design proposals
- Liaise with Tameside Council to understand prior approvals required
- Liaise with utility companies





Coal Customer Services Project Number P-041629 0345 762 6848 (Mon-Fri, 9am-5pm)

24/7 incident hotline 0800 288 4242

Email customerservice@coal.gov.uk

Twitter @coalauthority



Scan the code below to visit our Camberwell Drive website for more information on this project



Online: https://www2.groundstability.com/location/camberwell-drive/

