



Resolving the impacts of mining



Thank you for placing your order with the Coal Authority Mining Reports team.

Please find enclosed the Coal Authority's Non-Residential CON29M and Groundsure Screening Report.

The icon below summarises whether the Coal Authority consider that the following conditions may affect the ground stability at the report location. A fuller explanation of the condition and its potential to result in ground movement are given in the Coal Authority section of this report.



Coal mining

No

If you need any further assistance, please do not hesitate to contact our experts on **0345 762 6848** quoting the Coal Authority reference number.

Coal Authority ref: 71004720629002

Your ref:

Date: 17 October 2019

For any coal mining related issues please contact the Coal Authority:

0345 762 6848 groundstability@coal.gov.uk For all other issues and assistance please contact Groundsure:

0844 415 9000 info@groundsure.com





Issued by:

The Coal Authority, Property Search Services, 200 Lichfield Lane, Berry Hill, Mansfield, Nottinghamshire, NG18 4RG Website: www.groundstability.com Phone: 0345 762 6848

THE COAL AUTHORITY 200 LICHFIELD LANE MANSFIELD NOTTINGHAMSHIRE NG18 4RG Our reference: **71004720629002**

Your reference:

Date of your enquiry: 17 October 2019
Date we received your enquiry: 17 October 2019

Date of issue: 17 October 2019

This report is for the property described in the address below and the attached plan.

Non-Residential Enviro All-in-One - Off Coalfield

This report is based on and limited to the records held by, the Coal Authority, at the time we answer the search.

Coal mining	No
-------------	----

Information from the Coal Authority

The property lies outside any defined coalfield area.

Additional Remarks


Information provided by the Coal Authority in this report is compiled in response to the Law Society's CON29M Coal Mining enquiries. The said enquiries are protected by copyright owned by the Law Society of 113 Chancery Lane, London WC2A 1PL. This report is prepared in accordance with the Law Society's Guidance Notes 2018, the User Guide 2018 and the Coal Authority's Terms and Conditions applicable at the time the report was produced.

The Coal Authority owns the copyright in this report. The information we have used to write this report is protected by our database rights. All rights are reserved and unauthorised use is prohibited. If we provide a report for you, this does not mean that copyright and any other rights will pass to you. However, you can use the report for your own purposes.

Location map




Approximate position of property



Enquiry boundary

Reproduced by permission of Ordnance Survey on behalf of HMSO. © Crown copyright and database right 2018. All rights reserved. Ordnance Survey Licence number: 100020315

Approximate position of enquiry boundary shown



© The Coal Authority

Ordnance Survey

Non-Residential Enviro All-in-One - Off Coalfield - 71004720629002

Page 2 of 2

--

.



Professional opinion



Contaminated Land

Error: T3st R3p0rt

page 4



Flood Risk

Low

page 5

Consultant's guidance and recommendations inside.



Ground Stability

Identified

page 5



Radon

Passed



Energy

Identified

page 6



Planning Constraints

Identified

page 8



Transportation

Identified

page 7

A full assessment of transportation is available in our Energy and Transportation report. Contact Groundsure or your search provider for further details.

Site plan



Contaminated land liability

Banking security

Is it likely that the property will represent acceptable banking security from a contaminated land perspective?

Error

Statutory or 3rd party action

Is there a risk of statutory (e.g. Part 2A EPA 1990) or third party action being taken against the site?

Error

Environmental liability

Is there a risk that the property value may be impacted due to contaminated land liability issues?

Error





Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774 **Date**: 17 October 2019

: 71004720629002

Your ref: -

Grid ref: 522479 208774

Useful contacts

Welwyn Hatfield Council: http://www.welhat.gov.uk/ contact-WHC@welhat.gov.uk 01707 357 000 Environment Agency National Customer Contact Centre (NCCC): enquiries@environment-agency.gov.uk 03708 506 506

Overview of findings and recommendations

To save you time when assessing the report, we only provide maps and data tables of features within the search radius that we have identified to be of note. These relate to environmental risks that may have liability implications, affect insurance premiums, property values and/or a lender's willingness to lend.

You can view the fully comprehensive library of information we have searched on page 33.



Flood Risk

Groundwater Flooding

A risk of groundwater flooding has been identified at the site. This will be more of an issue for properties with a basement or other section below ground. Further advice on groundwater flooding has been produced by the Environment Agency and the Local Government Association and can be found at

https://assets.publishing.service.gov.uk/government/uploads/system/uploads/attachment_data/file/297421/flho0911bugi-e-e.pdf

National Planning Policy Framework (NPPF)

A site-specific flood risk assessment should be provided for all development in Flood Zones 2 and 3. In Flood Zone 1, an assessment should accompany all proposals involving: sites of 1 hectare or more; land which has been identified by the Environment Agency as having critical drainage problems; land identified in a strategic flood risk assessment as being at increased flood risk in future; or land that may be subject to other sources of flooding, where its development would introduce a more vulnerable use. The NPPF states that the flood risk assessment should identify and assess the risks of all forms of flooding to and from the development and demonstrate how these flood risks will be managed so that the development remains safe throughout its lifetime, taking climate change into account. Those proposing developments should take advice from the emergency services when producing an evacuation plan for the development as part of the flood risk assessment.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774



Ground stability

The property is indicated to lie within an area that could be affected by mining other than coal. You should consider the following:

- carry out a visual inspection of the property looking out for cracks and other signs of subsidence
- have a structural survey conducted by a Structural Surveyor to clarify whether or not the property is being affected by any of the risks presented in this report
- contact the relevant Local Authority departments (e.g Planning department, Building Regulations) to ask for records of the property and local area relating to subsidence
- remember that professional advice should be sought before altering the ground in any way at the property, including the planting of trees

Other considerations

These are next steps associated with non-environmental search returns on matters of energy and transport infrastructure, mobile masts, and planning constraints.



Energy

Wind

Existing or proposed wind installations have been identified within 5km. Next steps for consideration:

- use the details given in the report to find out more about the potential impacts on the property
- contact the operating company and the relevant Local Authority for further information
- visit the area in order to more accurately assess the impact this wind development would have on the property

Solar

Existing or proposed solar installations have been identified within 5km of the property. Next steps for consideration:

- use the details given in the report to find out more about the potential impacts on the property by contacting the operating company and/or Local Authority
- visit the area in order to more accurately assess the impact this solar farm would have on the property



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Consultant's assessment



Environmental searches are designed to ensure that significant hazards and risks associated with this property are identified and considered alongside the investment in or purchase of a property. Please see page 2 for further advice.



Contaminated Land

The Contaminated Land assessment has been completed by a qualified environmental consultant.

Please see page 12 for details of the identified issues.

Past Land Use Error
Waste and Landfill Error
Current and Recent Industrial Error

Site setting

Conclusion

Groundsure has identified that this is a test report.





Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Environmental summary





Flood Risk

Property's overall risk assessment for river, coastal, surface water and groundwater flooding is low.

Further explanation of flood risk assessment can be seen in the Flood information on page 38.

River and Coastal Flooding

Groundwater Flooding

Surface Water Flooding

FloodScore™

Past Flooding

Flood Storage Areas

NPPF Flood Risk Assessment

Very Low

Not identified

Not identified

Not identified

Ground stability

The property is assessed to have potential for natural or non-natural ground subsidence.

Please see page 26 for details of the identified issues.

Natural Ground Stability

required if site redeveloped?

Negligible-Very

low

Non-Natural Ground Stability Identified

Date: 17 October 2019



Radon

Local levels of radon are considered normal. Percentage of affected homes in your local area is: Less than 1%.

Not in a radon affected area



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Energy summary





Oil and Gas

No historical, active or planned wells or extraction areas (such as fracking sites) identified near the property.

Oil and Gas Areas
Oil and Gas Wells

Not identified

Not identified



Wind and Solar

Our search of existing and planned renewable wind and solar infrastructure has identified results.

Please see page 2 for further advice. Additionally, see page 27 for details of the identified issues.

Planned Multiple Wind Turbines

Planned Single Wind Turbines
Existing Wind Turbines
Proposed Solar Farms
Existing Solar Farms

Identified

Identified
Not identified
Not identified
Identified



Energy

Our search of major energy transmission or generation infrastructure and nationally significant infrastructure projects has not identified results.

Power stations
Energy Infrastructure
Projects

Not identified Not identified Not identified



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Transportation summary



The property has been identified to lie within the search radius of one or more transportation features detailed below.

If required, full details on these transportation features including a detailed location plan relative to the property are available when you purchase a Groundsure Energy and Transportation Report via your preferred searches provider.



HS2

No results for Phase 1 or Phase 2 of the HS2 project (including the 2016 amendments) have been identified within 5km of the property. However, HS2 routes are still under consultation and exact alignments may change in the future.

HS2 Route	Not identified
HS2 Safeguarding	Not identified
HS2 Stations	Not identified
HS2 Depots	Not identified
HS2 Noise	Not assessed
HS2 Visual impact	Not assessed



Crossrail

The property is not within 250 metres of either the Crossrail 1 or Crossrail 2 project.

Crossrail 1 Route	Not identified
Crossrail 1 Stations	Not identified
Crossrail 1 Worksites	Not identified
Crossrail 2 Route	Not identified
Crossrail 2 Stations	Not identified
Crossrail 2 Worksites	Not identified
Crossrail 2 Safeguarding	Not identified
Crossrail 2 Headhouse	Not identified



Other Railways

Our search indicates the property is within 250 metres of railways or railway stations, subway or DLR lines, active railways, historical railways or tunnels.

The Underground assessment includes London Underground, DLR, Tyne and Wear Metro, Merseyrail and Glasgow Subway.

Active Railways and Tunnels Historical Railways and Tunnels Railway and Tube Stations

Underground

Not identified Identified

Not identified Not identified



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Planning summary





Planning constraints

Protected areas have been identified within 250 metres of the property.

Please see page 31 for details of the identified issues.

Environmental Protected Areas Not identified
Visual and Cultural Protected Identified
Areas





Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Other environmental considerations



The following additional risks or issues are outside the scope of the opinion provided by this report. However, further consideration of these may be appropriate for the subject property.

Asbestos

The Control of Asbestos Regulations 2012 require an Asbestos Management Plan to be maintained for all commercial property constructed prior to 2000 i.e. where asbestos may be contained within the building fabric. Refurbishment or demolition of site structures may require further Refurbishment and Demolition Asbestos Surveys.

Site-specific features

This report has considered additional site specific information, where provided by the client, however it has not included a site inspection. Additional issues may exist at the property that cannot be reasonably identified by a desk based report like this one. Examples might include operational issues such as those linked to oil storage, waste management, materials handling and site drainage. Additional surveys and assessments may be required if these issues are considered to be a concern.

Unexploded ordnance (UXO)

The UK has a history of military activity, including extensive military training sites, bombing during the First World War and sustained strategic bombing during the Second World War. A legacy of this military activity is the incidence of UXO across Britain. Construction increases the risk from UXO. If intrusive works are planned on site, an assessment of the likelihood of UXO risk should be carried out in compliance with the Construction (Design and Management) Regulations 2015.

Environmental insurance

The ownership or possession of land and property is one of the most valuable assets an individual or organisation can have. In cases where we are unable to provide a low risk assessment with regards to contaminated land, environmental insurance should be considered. Environmental insurance can protect against regulatory and third party action, potential losses and additional costs in dealing with contamination. Independent, specialist brokers are able to access the entire environmental insurance market, providing bespoke environmental policies to address risk and transactional issues.

Phase 1 environmental risk assessment

A Phase 1 environmental risk assessment (Contaminated Land) aims to clarify any identified environmental risks further or could support a planning application. It includes a site inspection, regulatory consultation and additional details of site context. Our expert analysis provides a detailed breakdown of each potential exposure pathway and suggested mitigation measures. For further information or to request a quote please e-mail us at projects@groundsure.com. The reports start from £1195+VAT, which includes a discount for current reporting.

Made ground and infilled land

Areas of made ground and infilled land can settle over time and could potentially cause subsidence. If the property is known to be located on made or infilled ground it would be prudent to contact a RICS accredited surveyor and/or geotechnical engineer to clarify any structural/subsidence risks and determine if possible what materials were used during the infilling process.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Recent aerial photograph





Capture Date: 23/07/2016

Site Area: 0.02ha



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Contaminated Land summary



Past land use	On-Site	0-50m	50-250m
Former industrial land use (1:10,560 and 1:10,000 scale)	0	0	16
Former tanks	0	0	18
Former energy features	0	6	16
Former petrol stations	0	0	0
Former garages	0	0	4
Former military land	0	0	0

Waste and landfill	On-Site 0-50m 50-250m
Active or recent landfill	0 0
Former landfill (from Environment Agency Records)	0 0 0
Former landfill (from Local Authority and historical mapping records)	0 0 0
Waste site no longer in use	0 0 0
Active or recent licensed waste sites	0 0 0

Current and recent industrial	On-Site	0-50m	50-250m
Recent industrial land uses	0	1	12
Current or recent petrol stations	0	1	0
Historical licensed industrial activities	0	0	0
Current or recent licensed industrial activities	0	0	0
Local Authority licensed pollutant release	0	0	1
Pollutant release to surface waters	0	0	0
Pollutant release to public sewer	0	0	0
Dangerous industrial substances (D.S.I. List 1)	0	0	0
Dangerous industrial substances (D.S.I. List 2)	0	0	0
Dangerous or explosive sites	0	0	0
Hazardous substance storage/usage	0	0	0
Sites designated as Contaminated Land	0	0	0
Pollution incidents	0	1	1



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Contaminated Land



Past land use



Former industrial land use (1:10,560 and 1:10,000 scale)

These historical land uses have been identified from 1:10,560 and 1:10,000 scale Ordnance Survey maps dated from the mid to late 1800s to recent times. They have the potential to have caused ground contamination. Please see the Environmental Summary to find out how these could impact the site.

Please see page 2 for further advice.

Distance	Direction	Use	Date
63 m	NE	Unspecified Workhouse	1879
78 m	N	Laundry	1922
78 m	N	Laundry	1939
84 m	N	Laundry	1922



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Distance	Direction	Use	Date
98 m	NE	Unspecified Workhouse	1896
121 m	N	Unspecified Works	1988
124 m	NE	Cemetery	1896
124 m	NE	Cemetery	1922
124 m	NE	Cemetery	1939
126 m	NE	Cemetery	1922
127 m	NE	Cemetery	1879
127 m	NE	Cemetery	1971
127 m	NE	Cemetery	1973
127 m	NE	Cemetery	1988
164 m	N	Unspecified Works	1973
246 m	SW	Smithy	1896

This data is sourced from Ordnance Survey/Groundsure.

Former tanks

These tanks have been identified from high detailed historical Ordnance Survey maps dating from the mid-late 1800s to recent times. Tanks like this can sometimes store harmful waste, chemicals or oil, as well as more benign substances. Liquids stored in these tanks can leak when the tanks rust or become damaged over time, which could have caused contamination at this site.

Please see page 2 for further advice.

Distance	Direction	Ușe	Date
83 m	SE	Unspecified Tank	1981
117 m	N	Unspecified Tank	1981
118 m	NE	Unspecified Tank	1961
118 m	NE	Unspecified Tank	1968
118 m	NE	Unspecified Tank	1981
119 m	NE	Unspecified Tank	1978
119 m	NE	Unspecified Tank	1960
119 m	NE	Unspecified Tank	1969
120 m	Е	Unspecified Tank	1981



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Distance	Direction	Use	Date
121 m	NE	Tanks	1968
121 m	NE	Tanks	1981
121 m	NE	Tanks	1978
122 m	NE	Tanks	1969
148 m	N	Tanks	1981
148 m	N	Unspecified Tank	1968
149 m	N	Unspecified Tank	1978
149 m	N	Unspecified Tank	1969
151 m	SW	Unspecified Tank	1879

This data is sourced from Ordnance Survey/Groundsure.

Former energy features

Energy features such as substations, transformers or power stations have been identified from high detailed historical Ordnance Survey maps dating from the mid to late 1800s to recent times. Structures like this can sometimes cause soil or groundwater contamination.

Please see page 2 for further advice.

Distance	Direction	Use	Date
10 m	SW	Electricity Substation	1993
10 m	SW	Electricity Substation	1995
10 m	SW	Electricity Substation	1969
11 m	SW	Electricity Substation	1970
11 m	SW	Electricity Substation	1980
12 m	SW	Electricity Substation	1989
143 m	NW	Electricity Substation	1970
143 m	NW	Electricity Substation	1980
144 m	NW	Electricity Substation	1969
144 m	NW	Electricity Substation	1989
144 m	NW	Electricity Substation	1993
144 m	NW	Electricity Substation	1995
188 m	S	Electricity Substation	1989



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Distance	Direction	Use	Date
198 m	S	Electricity Substation	1993
198 m	S	Electricity Substation	1995
199 m	S	Electricity Substation	1969
200 m	S	Electricity Substation	1970
200 m	S	Electricity Substation	1980
208 m	SE	Electricity Substation	1969
208 m	SE	Electricity Substation	1978
208 m	SE	Electricity Substation	1968
208 m	SE	Electricity Substation	1981

This data is sourced from Ordnance Survey/Groundsure.

Former garages

These garages have been identified from high detailed historical Ordnance Survey maps dating from the mid to late 1800s to recent times. They have the potential to cause ground contamination. This can be because spills can occur when fuel, oil or solvents are used causing ongoing pollution. Older and obsolete garages are considered a greater risk than newer ones, as tanks can remain underground and deteriorate, sometimes causing significant leaks.

Please see page 2 for further advice,

Distance	Direction	Use	Date
153 m	SW	Garage	1993
153 m	SW	Garage	1995
154 m	SW	Garage	1980
154 m	SW	Garage	1989

This data is sourced from Ordnance Survey/Groundsure.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Current and recent industrial



Recent industrial land uses

These records show details of businesses that have recently operated, or are currently operating in the area. Depending on the type of activities taking place, some of these businesses could present a risk of contamination.

Please see page 2 for further advice.

ID	Distance	Direction	Company / Address	Activity	Category
2	15 m	SW	Electricity Sub Station - Hertfordshire, AL10	Electrical Features	Infrastructure and Facilities
4	83 m	SW	Specsavers Hearcare - 80, Town Centre, Hatfield, Hertfordshire, AL10 0JW	Disability and Mobility Equipment	Consumer Products
5	84 m	NE	Laptop Repair Hatfield - 49, St. Lukes Court, Hatfield, Hertfordshire, AL10 0FD	Electrical Equipment Repair and Servicing	Repair and Servicing
7	133 m	NE	Electricity Sub Station - Hertfordshire, AL10	Electrical Features	Infrastructure and Facilities

Contact us with any questions at:

info@groundsure.com 08444 159 000



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

ID	Distance	Direction	Company / Address	Activity	Category
8	147 m	N	Electricity Sub Station - Hertfordshire, AL10	Electrical Features	Infrastructure and Facilities
9	147 m	S	Twist & Go Motorcycles - 13, Market Place, Hatfield, Hertfordshire, AL10 OLJ	Vehicle Repair, Testing and Servicing	Repair and Servicing
11	158 m	S	Welwyn Hatfield Mobile Shop - 23a, Market Place, Hatfield, Hertfordshire, AL10 OLJ	Electrical Equipment Repair and Servicing	Repair and Servicing
12	191 m	N	Factory - Hertfordshire, AL10	Unspecified Works Or Factories	Industrial Features
13	201 m	S	Electricity Sub Station - Hertfordshire, AL10	Electrical Features	Infrastructure and Facilities
14	205 m	N	Caressa Kahn - Wellfield Road, Hatfield, Hertfordshire, AL10 OBS	Cosmetics, Toiletries and Perfumes	Consumer Products
14	205 m 213 m	N SE			
			Hertfordshire, AL10 0BS	Perfumes	Products Infrastructure and

This data is sourced from Ordnance Survey.

Current or recent petrol stations

Petrol stations and their associated storage tanks are considered a risk for soil and groundwater contamination. This is because spills can occur when fuel tanks are filled and leaks from these tanks can cause ongoing pollution. Older and obsolete petrol stations are considered a greater risk than newer ones, as fuel tanks can remain underground and deteriorate, sometimes causing significant leaks. In some cases, fuels such as petrol or diesel can spread beneath the surface, meaning that properties can be affected even when they are some distance away.

Please see page 2 for further advice.

ID	Distance	Direction	Company	Address	Status
1	10 m	SW	OBSOLETE		Obsolete

This data is sourced from Experian Catalist.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Local Authority licensed pollutant release

Industrial facilities that release pollutants to the environment (air, land or water) may be regulated by the Local Authority and hold a Part A(2) or Part B process authorisation or licence. These processes could include the burning of waste oils, paint spraying and petrol vapour recovery. There could be a risk of ground contamination if harmful materials associated with these processes are not stored and handled correctly.

Please see page 2 for further advice.

ID	Distance	Direction	Address	Local Authority	Processes Undertaken	Permit Type	Details of Enforcement
6	115 m	SE		Welwyn Hatfield Borough Council	Dry Cleaning	Part B	Enforcement: No Enforcements Notified Date of Enforcement: No Enforcements Notified Comment: No Enforcements Notified

This data is sourced from Local Authorities.

Pollution incidents

Environment Agency keep records of all major or significant pollution incidents that are known to have impacted the land, water or air. The location provided for these records may relate to the location of the incidents but may sometimes be recorded where the effects of the incident was reported.

Please see page 2 for further advice.

ID	Distance	Direction	Incident Date	Land Impact	Water Impact	Pollutant
3	29 m	SE	17/10/2001	Category 4 (No Impact)	Category 4 (No Impact)	Other Contaminated Water
10	149 m	SE	17/05/2002	Category 3 (Minor)	Category 4 (No Impact)	Other Oil or Fuel

This data is sourced from the Environment Agency/Natural Resources Wales.



Ref: 71004720629002

Your ref:

Grid ref: 522479 208774

Superficial hydrogeology





Aquifers within superficial geology

The Environment Agency/Natural Resources Wales and the British Geological Survey have assigned designations or types to the aquifers that exist within superficial geology. These designations reflect the importance of aquifers in terms of groundwater as a resource (eg drinking water supply) but also their role in supporting surface water flows and wetland ecosystems.

Principal - These are layers of rock or superficial deposits that usually provide a high level of water storage.

Secondary A - Permeable layers capable of supporting water supplies at a local rather than strategic scale.

Secondary B - Predominantly lower permeability layers which may store and yield limited amounts of groundwater.

Secondary Undifferentiated - Has been assigned in cases where it has not been possible to attribute either category A or B to a rock type.

Unproductive - These are rock layers with low permeability that have negligible significance for water supply.

Unknown - These are rock layers where it has not been possible to classify the water storage potential.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

231 m	NW	Secondary Undifferentiated
0	on site	Secondary A
Distance	Direction	Designation

This data is sourced from the Environment Agency/Natural Resources Wales and the British Geological Survey.

Superficial geology

Superficial deposits are the youngest natural geological deposits formed during the most recent period of geological time. They rest on older deposits or rocks referred to as bedrock. This information comes from the BGS 1:50,000 Digital Geological Map of Great Britain, where available.

Description	BGS LEX Code	Rock Type
KESGRAVE CATCHMENT SUBGROUP	KGCA-XSV	SAND AND GRAVEL

This data is sourced from British Geological Survey.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Bedrock hydrogeology





Aquifers within bedrock geology

The Environment Agency/Natural Resources Wales and the British Geological Survey have assigned designations or types to the aquifers that exist within bedrock geology. These designations reflect the importance of aquifers in terms of groundwater as a resource (eg drinking water supply) but also their role in supporting surface water flows and wetland ecosystems.

Principal - These are layers of rock or superficial deposits that usually provide a high level of water storage.

Secondary A - Permeable layers capable of supporting water supplies at a local rather than strategic scale.

Secondary B - Predominantly lower permeability layers which may store and yield limited amounts of groundwater.

Secondary Undifferentiated - Has been assigned in cases where it has not been possible to attribute either category A or B to a rock type.

Unproductive - These are rock layers with low permeability that have negligible significance for water supply.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Distance	Direction	Designation
0	on site	Principal

This data is sourced from the Environment Agency/Natural Resources Wales and the British Geological Survey.

Bedrock geology

Bedrock geology is a term used for the main mass of rocks forming the Earth and is present everywhere, whether exposed at the surface in outcrops or concealed beneath superficial deposits or water. This information comes from the BGS 1:50,000 Digital Geological Map of Great Britain, where available.

Description		BGS LEX Code	Rock Type
LEWES NODULAR CHALK FORMATION AND SEAFORD CHALK FORMATION (UNDIFFERENTIATED)	◂	LESE-CHLK	CHALK

This data is sourced from British Geological Survey.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Source Protection Zones and drinking water abstractions





Source Protection Zones

The Environment Agency / Natural Resources Wales has defined Source Protection Zones (SPZs) for groundwater sources such as wells, boreholes and springs used for public drinking water supply. These zones show the risk of contamination from any activities that might cause pollution in the area. The closer the activity, the greater the risk. There are three main zones (inner (SPZ 1), outer (SPZ 2) and total catchment (SPZ 3)) and a fourth zone of special interest.

Distance	Direction	Details
0	on site	Zone: 3 Description: Total catchment
82 m	SW	Zone: 2 Description: Outer catchment



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

This data is sourced from the Environment Agency/Natural Resources Wales.





08444 159 000

Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Flood Risk



Groundwater flooding



Ambiental data indicates that the property is in an area with a moderate risk of groundwater flooding. Should a 1 in 100-year groundwater flood event occur, groundwater levels may affect basement areas. Properties without basements are are not considered to be at risk from this level of groundwater flooding.

Some of the responses contained in this report are based on data and information provided by the Natural Environment Research Council (NERC) or its component body British Geological Survey (BGS). Your use of any information contained in this report which is derived from or based upon such data and information is at your own risk. Neither NERC nor BGS gives any warranty, condition or representation as to the quality, accuracy or completeness of such information and all liability (including for negligence) arising from its use is excluded to the fullest extent permitted by law. Your use of the data/report/assessment constitutes your agreement to bring no claim against NERC or BGS in connection with it.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Ground stability



Non-natural ground subsidence

Mining cavities

There is a hole or cavity caused by mining close to the property. Such mining cavities may cause ground stability problems such as subsidence, surface collapses, mass movement and landslides, depending on the style of mining used. However, this does not confirm whether the property will be directly affected.

Please see page 2 for further advice.

Distance	Direction	Address	Bedrock Deposits	Type of Mining
194 m	SE	Hatfield, Hertfordshire	Chalk Group	Chalk

The above Mining Cavities information is provided by Peter Brett Associates.



Ref: 71004720629002


Your ref: -

Grid ref: 522479 208774

Energy



Wind and solar



Wind

Proposed wind farms

A wind farm or group of turbines or individual wind turbine has been proposed within 5,000m of the property. See below for details of the operating company, number of turbines, project and turbine capacity.

Please note some planning applications identified as having been refused, may have subsequently been granted on appeal without appearing as such within this report. Additionally, please be aware that as the identified records are taken from a planning record archive, the proposals identified may have already been undertaken.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

ID	Distance	Direction	Details	
1	1-2 km	SW	Planning Application Reference: S6/2012/1022/FP Type of Project: 2 Wind Turbines	Application Date: 2012-05-09 Planning Stage: Plans Approved Detail Plans Granted Project Details: Scheme comprises Formation of 2 wind turbines and 27 photovoltaic panels on roof. Approximate Grid Reference: 521435, 207482

This information is derived from planning data supplied by Glenigan, in some cases with further accuracy applied by Groundsure's experts. This search includes planning applications for wind farms with multiple turbines within 5,000m of the property. This data is updated on a quarterly basis. If the existence of a planning application, passed or refused may have a material impact with regard to the decision to purchase the property, Groundsure recommends independent, thorough enquiries are made with the Local Authority. If any applications have been identified within this report, Groundsure have included the planning reference to enable further enquiries to be made.

Proposed wind turbines

Planning applications for individual wind turbines have been proposed within 5,000m of the property. See below for details of the operating company, number of turbines, project and turbine capacity.

Please note some planning applications identified as having been refused may have subsequently been granted on appeal without appearing as such within this report. Additionally, please be aware that as the identified records are taken from a planning record archive, the proposals identified may have already been undertaken.

ID	Distance	Direction	Details	
2	1-2 km	SW	Planning Application Reference: S6/2007/1266/FP Type of Project: Wind Turbine & Solar Panels	Application Date: 2007-08-21 Planning Stage: Plans Approved Detail Plans Granted Project Details: Scheme comprises construction of small wind turbine (1.8m diameter) and 2 solar panels on roof. Approximate Grid Reference: 521434, 207482
4	3-4 km	SW	Site Name: Planning Application Reference: 5/2006/1246 Type of Project: Wind Turbine	Application Date: 2006-06-23 Planning Stage: Plans Approved Detail Plans Granted Project Details: Scheme comprises installation of wind turbine (resubmission following withdrawal of 5/05/2527DC). Approximate Grid Reference: 519944, 206772



40 TOWN CENTRE, HATFIELD, HERTFORDSHIRE, AL10 0JJ

Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

ID	Distance	Direction	Details	
5	3-4 km	SW	Site Name: 7 Planning Application Reference: 5/2005/2527 DC Type of Project: Wind Turbine	Application Date: 2005-12-23 Planning Stage: Early Planning Detailed Plans Submitted Project Details: Scheme comprises wind turbine. Approximate Grid Reference: 519944, 206772
6	3-4 km	SW	Site Name: : 5/2010/2747 Type of Project: Wind Turbine	Application Date: 2010-11-16 Planning Stage: Plans Approved Detail Plans Granted Project Details: Scheme comprises installation of one 11kw wind turbine with a maximum ground to tip height of 24.8m (resubmission following refusal of 5/2010/1587, dated 22/10/2010). Approximate Grid Reference: 520462, 205906
7	3-4 km	SW	Site Name: Reference: 5/2010/1587 Type of Project: Wind Turbine	Application Date: 2010-06-29 Planning Stage: Early Planning Detail Plans Refused Project Details: Scheme comprises installation of one 11kw wind turbine with a maximum ground to tip height of 24.5m. Approximate Grid Reference: 520462, 205906

This information is derived from planning data supplied by Glenigan, in some cases with further accuracy applied by Groundsure's experts. This search includes planning applications for single wind turbines only, within 5,000m of the property. This data is updated on a quarterly basis.

If the existence of a planning application, passed or refused, may have a material impact with regard to the decision to purchase the property, Groundsure recommends independent, thorough enquiries are made with the Local Authority. If any applications have been identified within this report, Groundsure have included the planning reference to enable further enquiries to be made.

Solar

Existing and agreed solar installations

There is an operational or planned solar photovoltaic farm or smaller installation located near the property.

Please note this will not include small domestic solar installations. See below for details on installed capacity, operating company and the status of the project on a given date.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

ID	Distance	Direction	Address	Details	
3	1-2 km	NW		Contractor: Computacenter UK LPA Name: Welwyn Hatfield Borough Council Capacity (MW): 2	Application Date: 29/01/2019 Pre Consent Status: Planning Permission Granted Post Consent Status: Awaiting Construction Date Commenced: -

The solar installation data is supplied by the Department for Business, Energy & Industrial Strategy and is updated on a monthly basis.






Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Planning Constraints





Visual and Cultural Designations

Listed Buildings

The presence of listed buildings means there will be extra control over what changes can be made to that building's interior and exterior. If the property itself is a listed building, owners will need to apply for Listed Building Consent for most types of work that affect the 'special architectural or historic interest' of the property and the work approved may increase costs.

Distance	Direction	Name	Grade	Listed building reference number	Listed date
196 m	E	Church Of St Luke	II	1101002	09/12/1983



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

This data is sourced from Historic England. For more information please see https://historicengland.org.uk/listing/the-list/





08444 159 000

Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Datasets searched

This is a full list of the data searched in this report. If we have found results of note we will state "Identified". If no results of note are found, we will state "Not identified". Our intelligent filtering will hide "Not identified" sections to speed up your workflow.

Contaminated Land	
Former industrial land use (1:10,560 and 1:10,000 scale)	Identified
Former tanks	Identified
Former energy features	Identified
Former petrol stations	Not identified
Former garages	Identified
Former military land	Not identified
Former landfill (from Local Authority and historical mapping records)	Not identified
Waste site no longer in use	Not identified
Active or recent landfill	Not identified
Former landfill (from Environment Agency Records)	Not identified
Active or recent licensed waste sites	Not identified
Recent industrial land uses	Identified
Current or recent petrol stations	Identified
Dangerous or explosive sites	Not identified
Hazardous substance storage/usage	Not identified
Sites designated as Contaminated Land	Not identified
Historical licensed industrial activities	Not identified
Current or recent licensed industrial activities	Not identified
Local Authority licensed pollutant release	Identified
	Not identified
Pollutant release to surface waters	Not identified

Contaminated Land	
Dangerous industrial substances (D.\$.I. List 1)	Not identified
Dangerous industrial substances (D.S.I. List 2)	Not identified
Pollution incidents	Identified
Superficial hydrogeology	
Aquifers within superficial geology	Identified
Superficial geology	Identified
Bedrock hydrogeology	
Aquifers within bedrock geology	Identified
Groundwater abstraction licences	Not identified
Bedrock geology	Identified

Source Protection Zones and drinking water abstractions

Source Protection Zones	Identified
Source Protection Zones in confined aquifer	Not identified
Drinking water abstraction licences	Not identified
Hydrology	
Water courses from Ordnance Survey	Not identified
Surface water abstractions	Not identified
Flood Risk	
Risk of flooding from rivers and the sea	Not identified



info@groundsure.com 08444 159 000

Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Flood Risk	
Flood storage areas: part of floodplain	Not identified
Historical flood areas	Not identified
Areas benefiting from flood defences	Not identified
Flood defences	Not identified
Proposed flood defences	Not identified
Surface water flood risk	Not identified
Groundwater flooding	Identified
Ground stability	
Natural ground subsidence	Not identified
Natural geological cavities	Not identified
Coal mining	Not identified
Non-coal mining	Not identified
Mining cavities	Identified
Infilled land	Not identified
Radon	
Radon	Not identified
Oil and Gas	
Oil or gas drilling well	Not identified
Proposed oil or gas drilling well	Not identified
Licensed blocks	Not identified
Potential future exploration areas	Not identified
Wind and solar	
Wind farms	Not identified
Proposed wind farms	Identified
Proposed wind turbines	Identified

Wind and solar	
Proposed solar installations	Not identified
Energy Infrastructure	
Electricity transmission lines and pylons	Not identified
National Grid energy infrastructure	Not identified
Power stations	Not identified
Nuclear installations	Not identified
Large Energy Projects	Not identified
Planning constraints	
Sites of Special Scientific Interest	Not identified
Internationally important wetland sites (Ramsar Sites)	Not identified
Special Areas of Conservation	Not identified
Special Protection Areas (for birds)	Not identified
National Nature Reserves	Not identified
Local Nature Reserves	Not identified
Designated Ancient Woodland	Not identified
Green Belt	Not identified
World Heritage Sites	Not identified
Areas of Outstanding Natural Beauty	Not identified
National Parks	Not identified
Conservation Areas	Not identified
Listed Buildings	Identified
Certificates of Immunity from Listing	Not identified
Scheduled Monuments	Not identified
Registered Parks and Gardens	Not identified



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Contaminated Land assessment methodology

Environmental risk framework

This report is designed to provide a basic environmental liability risk assessment for the purposes of transaction due diligence, financing arrangements and similar circumstances. The report comprises a basic risk assessment within the general principles of the contaminant-pathway-receptor pollutant linkage model and with due regard for relevant publications issued by the Department of Environment, Food and Rural Affairs (and predecessor government departments) the British Standards Institute and the European Union.

Explicit opinion is provided with regard to potential liability for the property to be identified as Contaminated Land in accordance with the meaning set out in Part 2A of the Environmental Protection Act 1990. Consideration and due regard is also made of associated legislation that may lead to related statutory or third party environmental liability, including but not limited to the Water Resources Act 1991, the Water Act 2014, the Contaminated Land Regulations 2006, Environmental Permitting Regulations 2010, the Environmental Damage (Prevention and Remediation) (England) (Amendment) Regulations 2015 in England and the Environmental Damage (Prevention and Remediation) (Amendment) (Wales) Regulations 2015 in Wales.

This report does not contain a detailed Conceptual Site Model as required in the National Planning Policy Framework, however, it may prove highly effective in determining whether such further assessment is appropriate.

The report is based upon the information contained in subsequent dataset sections. Some datasets have been generated by and are unique to Groundsure, whilst others are provided by recognised bodies including Environment Agency/Natural Resources Wales, British Geological Survey, Public Health England, Local Authorities, etc. Groundsure may also have been provided with further details regarding the site by the client and / or their advisers. In the absence of such, Groundsure has made a best estimation regarding current and proposed land use. This report and the risk assessment presented is based purely upon this information.

In undertaking this report Groundsure has not, unless explicitly stated to the contrary, undertaken a site inspection, site investigation, consulted directly with the Local Authority with specific regard to the subject property or reviewed existing environmental reports. Whilst every effort is made to consider likely environmental liabilities on the basis of the information assessed, certain issues may only be readily discernible from physical site inspection and / or investigation.

Contaminant source - Pathway - Receptor definitions

Contaminant sources include (but are not limited to):

- Historical on-site and historical off-site sources (works, factories, oil tanks, landfill sites)
- Current on-site and current off-site sources (petrol stations, industrial facilities)

Pathways comprise:

Any mechanisms facilitating 'receptor' exposure to contaminative 'sources'

Receptors include:

Human health i.e. site users or occupiers, adjacent site users or occupiers



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

- Controlled Waters i.e. groundwater, surface water (rivers and streams etc)
- Habitats and biodiversity (in particular nature reserves or other designated sensitive habitats)
- Property, buildings and infrastructure

Environmental risk assessment definitions

A risk rating will be provided on the front page of the report depending on the level of environmental liability that there has been assessed to be at the site. The ratings are defined as follows:

Low: There are unlikely to be significant environmental liabilities associated with the property.

Low to Moderate: There are unlikely to be significant environmental liabilities associated with the property with regard to the proposed use. However, minor issues may require further consideration and assessment under certain circumstances e.g. redevelopment.

Moderate: Some potential environmental liabilities are likely to reside with the property as a result of historical and / or current use. Whilst unlikely to represent an immediate significant issue, if left unchecked this position may change with time. A prudent purchaser may wish to make further enquiries of the vendor / undertake limited further due diligence / seek environmental improvements. Redevelopment of the site will likely require further, more detailed assessment.

Moderate to High: Some potential significant environmental liability issues have been identified at the property requiring further assessment. Should further information be available it may be possible to re-assess the risk. In the absence of sufficient further information, further assessment might comprise consultation with the environmental regulators / review of existing environmental reports / commissioning new environmental reports / consideration of environmental insurance.

High: Significant potential environmental liabilities have been identified at the property. Further detailed environmental due diligence will likely be required and may include review of existing environmental reports / commissioning new environmental reports including site investigations / consideration of environmental insurance / transaction restructuring.

Is there a risk of statutory (e.g. Part 2A EPA 1990) or third party action being taken against the site? This response considers the risk of legal liability arising through ownership or occupation and use of the property through statutory or other third party claims.

Does the property represent Acceptable Banking Security from an environmental risk perspective? Consideration is given to the suitability of the property as robust financial security for the purposes of secured lending facilities. An assumption is made here that the subject property is being considered in isolation and that normal commercial lending loan to value ratios are being considered.

Groundsure may in certain circumstances be able to make a specific lender liability assessment based on a full view of financial arrangements and hence the commercial context of the environmental risks.

Is there a risk that the property value may be impacted due to environmental liability issues?

This response sets out to advise whether environmental liabilities are likely to materially impact upon a standard Royal Institution of Chartered Surveyors valuation of the property necessitating further assessment.

Environmental Damage (Prevention and Remediation) Regulations 2015

The Environmental Damage (Prevention and Remediation) (England) (Amendment) Regulations 2015, the Environmental Damage (Prevention and Remediation) (Amendment) (Wales) Regulations 2015 and the Environmental Liability (Scotland) Amendment Regulations 2015 came into force on 19th July 2015, and amend the Environmental Damage (Prevention and Remediation) Regulations 2009, which came into force in



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

England on 1st March 2009, in Wales on 6th May 2009 and in Scotland on 24th June 2009. These regulations implement the European Directive on Environmental Liability (2004/35/EC) and are aimed at ensuring responsible parties prevent and remedy environmental damage to the following receptors:

- Sites of Special Scientific Interest (SSSIs), other protected habitats and protected species
- Surface waters
- Groundwater
- Land, if contamination of the land results in significant risk of adverse effects on human health

The regulations are based on the 'polluter pays' principle and ensures that those responsible for causing environmental damage are those responsible for paying to prevent and remedy such damage. 'Environmental Damage' has a specific meaning within the Regulations, and covers only the most serious cases. For damage to SSSIs, EU protected species and habitats and damage to water, primary remediation, complementary remediation and compensatory remediation may be required by the enforcing authorities (Environment Agency/Natural Resources Wales, Scottish Environment Protection Agency (SEPA), Local Authorities, the Marine Fisheries Agency, Marine Scotland, Welsh Ministers and Natural England/Natural Resources Wales/Scottish Natural Heritage).

The regulations apply on land in England, Wales and Scotland, 1 nautical mile seaward from the baseline (in relation to water damage), on the seabed around the UK up to the limits set out in the Continental Shelf Act 1964, and to waters in the Renewable Energy Zone, which extends approximately 200 miles out to sea (in relation to protected species and natural habitats). These regulations are designed to work in tandem with Part 2A of the Environmental Protection Act, and only apply to environmental damage caused after the Regulations came into force. Groundsure's assessment of the site is not an assessment of the potential for Environmental Damage to occur at the site, but is an assessment of the sensitivity of the site in relation to relevant receptors.



Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Flood information

The Flood Risk Assessment section is based on datasets covering a variety of different flooding types. No inspection of the property or of the surrounding area has been undertaken by Groundsure or the data providers. The modelling of flood hazards is extremely complex and in creating a national dataset certain assumptions have been made and all such datasets will have limitations. These datasets should be used to give an indication of relative flood risk rather than a definitive answer. Local actions and minor variations, such as blocked drains or streams etc. can greatly alter the effect of flooding. A low or negligible modelled flood risk does not guarantee that flooding will not occur. Nor will a high risk mean that flooding definitely will occur. Groundsure's overall flood risk assessment takes account of the cumulative risk of river, coastal, surface water (pluvial), and groundwater flooding and historic flood events.

Risk of flooding from rivers and the sea

This is an assessment of flood risk for England and Wales produced using local data and expertise, provided by Environment Agency. It shows the chance of flooding from rivers or the sea presented in categories taking account of flood defences and the condition those defences are in. The model uses local water level and flood defence data to model flood risk.

Historic flood events

Over 86,000 events are recorded within this database. This data is used to understand where flooding has occurred in the past and provides details as available. Absence of a historic flood event for an area does not mean that the area has never flooded, but only that Environment Agency/Natural Resources Wales do not currently have records of flooding within the area. Equally, a record of a flood footprint in previous years does not mean that an area will flood again, and this information does not take account of flood management schemes and improved flood defences.

Surface water flooding

Ambiental Risk Analytics surface water flood map identifies areas likely to flood following extreme rainfall events, i.e. land naturally vulnerable to surface water or "pluvial" flooding. This data set was produced by simulating 1 in 30 year, 1 in 100 year, 1 in 250 year and 1 in 1000 year rainfall events. Modern urban drainage systems are typically built to cope with rainfall events between 1 in 20 and 1 in 30 years, though older ones may even flood in a 1 in 5 year rainstorm event.

Proposed flood defences

The data includes all Environment Agency/Natural Resources Wales's projects over £100K that will change or sustain the standards of flood defence in England and Wales over the next 5 years. It also includes the equivalent schemes for all Local Authority and Internal Drainage Boards.

Flood storage areas

Flood Storage Areas may also act as flood defences. A flood storage area may also be referred to as a balancing reservoir, storage basin or balancing pond. Its purpose is to attenuate an incoming flood peak to a flow level that can be accepted by the downstream channel. It may also delay the timing of a flood peak so that its volume is discharged over a longer time interval. These areas are also referred to as Zone 3b or 'the functional floodplain' and has a 5% or greater chance of flooding in any given year, or is designed to flood in the event of an extreme (0.1%) flood or another probability which may be agreed between the Local Planning Authority and Environment Agency/Natural Resources Wales, including water conveyance routes. Development within Flood Storage Areas is severely restricted.





Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

Groundwater flooding

Groundwater flooding is flooding caused by unusually high groundwater levels. It occurs as excess water emerging at the ground surface or within underground structures such as basements. Groundwater flooding tends to be more persistent than surface water flooding, in some cases lasting for weeks or months, and it can result in significant damage to property. This risk assessment is based on a 5m Digital Terrain Model (DTM) and 1 in 100 year and 1 in 250 year return periods.

Search Code and Groundsure terms and conditions

IMPORTANT CONSUMER PROTECTION INFORMATION

This search has been produced by Groundsure Ltd, Sovereign House, Church Street, Brighton, BN1 1UJ. Tel: 08444 159 000. Email: info@groundsure.com which is registered with the Property Codes Compliance Board (PCCB) as a subscriber to the Search Code. The PCCB independently monitors how registered search firms maintain compliance with the Code.

The Search Code

- provides protection for homebuyers, sellers, estate agents, conveyancers and mortgage lenders who rely on the information included in property search reports undertaken by subscribers on residential and commercial property within the United Kingdom
- sets out minimum standards which firms compiling and selling search reports have to meet
- promotes the best practice and quality standards within the industry for the benefit of consumers and property professionals
- enables consumers and property professionals to have confidence in firms which subscribe to the code, their products and services

By giving you this information, the search firm is confirming that they keep to the principles of the Code. This provides important protection for you.

The Code's core principles

Firms which subscribe to the Search Code will:

- display the Search Code logo prominently on their search reports
- act with integrity and carry out work with due skill, care and diligence
- at all times maintain adequate and appropriate insurance to protect consumers
- conduct business in an honest, fair and professional manner
- handle complaints speedily and fairly
- ensure that products and services comply with industry registration rules and standards and relevant laws
- monitor their compliance with the Code

Complaints Advice

If you have a query or complaint about your search, you should raise it directly with the search firm, and if appropriate ask for any complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response, after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Code.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPOs or to the PCCB.

TPO's Contact Details:

The Property Ombudsman scheme, Milford House, 43-55 Milford Street, Salisbury, Wiltshire SP1 2BP. Tel: 01722 333306 Fax: 01722 332296 Email: admin@tpos.co.uk Web: https://www.tpos.co.uk/

You can get more information about the PCCB from https://pccb.org.uk/.



Contact us with any questions at: Date: 17 October 2019

Ref: 71004720629002

Your ref: -

Grid ref: 522479 208774

PLEASE ASK YOUR SEARCH PROVIDER IF YOU WOULD LIKE A COPY OF THE SEARCH CODE

COMPLAINTS PROCEDURE: If you want to make a complaint, we will:

- acknowledge it within 5 working days of receipt
- normally deal with it fully and provide a final response, in writing, within 20 working days of receipt
- keep you informed by letter, telephone or e-mail, as you prefer, if we need more time
- provide a final response, in writing, at the latest within 40 working days of receipt
- liaise, at your request, with anyone acting formally on your behalf

Complaints should be sent to:

Operations Director, Groundsure Ltd, Sovereign House, Church Street, Brighton, BN1 1UJ. Tel: 08444 159 000. Email: info@groundsure.com If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman scheme (TPOs): Tel: 01722 333306, E-mail: admin@tpos.co.uk We will co-operate fully with the Ombudsman during an investigation and comply with their final decision.

Groundsure's Terms and Conditions can be viewed online at this link: https://www.groundsure.com/terms-and-conditions-feb11-2019

Important consumer protection information

All of the advice and reports that Groundsure produces are covered by a comprehensive Remediation Contribution policy to ensure customers are protected, see https://www.groundsure.com/remediation for full details.

Data providers

Groundsure works with respected data providers to bring you the most relevant and accurate information in your Screening report. To find out who they are and their areas of expertise see https://www.groundsure.com/sources-reference.

